


Work Order ID 161368

Monday, May 15, 2017 10:39:12 AM

161368

Page 1

Item ID: 647.7304 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: EC135 T2/P2 Cable Cutters System
Start Date: 5/15/2017 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 5/15/2017 Req'd Qty: 1.00 ***1*** Customer:
Reference: disassemble

Approvals: Process Plan:  Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
647.7300	C

110	Pick Kit	0.00
-----	----------	------

110

Packaging

Packaging

Memo

PULL FROM STOCK:
1 X 647.7304 B159888
DISASSEMBLE COMPLETELY
RETURN ALL ITEMS TO STOCK
USING ORIGINAL B/N'S

0.00

MAY 16 2017

DAS
6
9-89

140

QC21- Final Inspection - Work Order Release

0.00

140

QC

Quality Control

Memo

0.10

17/5/16 
17.05.17

Picklist Print

Monday, May 15, 2017 10:39:09 AM

Page 1

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP REV:A 16.04.27 NEW ISSUE DD VERF:JLM IPP
REV:B 16.11.15 dwg rev.c DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

600.0990		Purchased	No				Each	17.0000		-1			
----------	--	-----------	----	--	--	--	------	---------	--	----	--	--	--

600 0990

Magnabond 6398 Part A Size 112 ml

Location

Loc Qty

Loc Code

PKG

17

M136586

1

M136862

3

M137073

12

M134249

1

1/1/2017

600.0991		Purchased	No				Each	17.0000		-1			
----------	--	-----------	----	--	--	--	------	---------	--	----	--	--	--

600 0991

Magnabond 6398 Part B Size 112 ml

Location

Loc Qty

Loc Code

PKG

17

m136586

2

m136862

3

m137073

12

600.1012		Purchased	No				Each	24.0000		-1			
----------	--	-----------	----	--	--	--	------	---------	--	----	--	--	--

600 1012

Sealant PR1425B2 (#654 sem)

Location

Loc Qty

Loc Code

cck017

24

m136838

1

m1370073

1

m137321

8

m137371

14

8-89 DAS

MAY 15 2017

Picklist Print

Monday, May 15, 2017 10:39:09 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

601.2045 Purchased No

Each 9.0000 -1

601 2045

RTV (LOCTITE 598) McMaster p/n: 6641A41

MAY 15 2017
DAS 6
9-89

Location

Loc Qty

Loc Code

CCK096

1

m136902

1

GA

8

m134260

8

135628

601.2375 Manufactured No

Each 24.0000

601 2375

Washer

-3

MAY 15 2017

DAS 6
9-89

Location

Loc Qty

Loc Code

CCK096

24

91708

24

601.2999 Manufactured No

Each 25.0000

601 2999

Screw

-3

MAY 15 2017

DAS 6
9-89

Location

Loc Qty

Loc Code

CCK098

25

93369

25

601.3004 Purchased No

Each 4.0000

601 3004

Camloc Stud - 26S8-11

-2

MAY 15 2017

DAS 6
9-89

Location

Loc Qty

Loc Code

CCK098

4

M130388

4

2

Picklist Print

Monday, May 15, 2017 10:39:09 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

601.3005 Manufactured No

Each 16.0000

-2

MAY 15 2017

DAS
6
9-89

601 3005

Camloc Retainer - 2600-LW

Location

Loc Qty

Loc Code

CCK098

16

158642

16

2

601.3006

Purchased No

Each

4.0000

-2

MAY 15 2017

DAS
6
9-89

601 3006

Camloc Receptacle - 26R 16-1

Location

Loc Qty

Loc Code

CCK098

4

M130388

4

2

601.3011

Manufactured No

f

43.1000

-1.4

MAY 15 2017

DAS
3
9-89

601 3011

P-Seal

Location

Loc Qty

Loc Code

CCK095

43

91709

43

CCK099

0.1

M130388

0.1

1.4

601.3902

Manufactured No

Each

10.0000

-1

DAS
6
9-89

MAY 15 2017

601 3902

Eye Bolt

Location

Loc Qty

Loc Code

cck101

10

153184

10

147212 X1

1

Picklist Print

Monday, May 15, 2017 10:39:09 AM

Page 4

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

601.3902 Manufactured No

Each 10.0000 -1

601 3902

Eye Bolt

MAY 15 2017

DAS 6 9-89

Location

Loc Qty

Loc Code

cck101

10

153184

10

Each 51.0000

147012

-4

647.0112 Manufactured No

647 0112

Strut Bracket

MAY 15 2017

DAS 6 9-89

Location

Loc Qty

Loc Code

CCK106

51

159844

51

Each 1.0000

157352

-1

647.1601 Manufactured No

647 1601

Wiper Deflector Aft

DAS 6 9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK091

1

155569

1

Each 15.0000

148295

-1

647.1602 Manufactured No

647 1602

Doubler Assembly

DAS 6 9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK107

15

M130388

15

Each 5.0000

92479

-1

647.1610 Manufactured No

647 1610

Wiper Deflector Fwd

DAS 6 9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK091

5

125082

5

7

Monday, May 15, 2017 10:39:09 AM

Shop Packet Print

Page 4

Picklist Print

Monday, May 15, 2017 10:39:09 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

647.1702 Manufactured No

Each 3.0000 -2

647 1702

Skid Deflector Assembly

Location

Loc Qty

Loc Code

CCK033

3

154422

1

157781

2

647.1702 Manufactured No

Each 3.0000 -2

647 1702

Skid Deflector Assembly

Location

Loc Qty

Loc Code

CCK033

3

154422

1

157781

2

647.1702 Manufactured No

Each 3.0000 -1

647 1702

Skid Deflector Assembly

Location

Loc Qty

Loc Code

CCK033

3

154422

1

157781

2

647.1810 Manufactured No

Each 15.0000 -1

647 1810

Nose Door Doubler

Location

Loc Qty

Loc Code

CCK108

15

92070

1

M130388

14

DAS

6

9-89

MAY 15 2017

93380
92070

Picklist Print

Monday, May 15, 2017 10:39:09 AM

Page 6

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

647.1811 Manufactured No

Each 37.0000 -1

647 1811

Spacer

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK108

37

92072

3

M130388

34

647.1811 Manufactured No

Each 37.0000 -1

647 1811

Spacer

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK108

37

92072

3

M130388

34

647.1812 Manufactured No

Each 236.0000 -10

647 1812

Shim

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK107

236

92073

38

M130388

198

647.1812 Manufactured No

Each 236.0000 -2

647 1812

Shim

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK107

236

92073

38

M130388

198

Picklist Print

Monday, May 15, 2017 10:39:09 AM

Page 7

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

647.1812 Manufactured No

Each 236.0000 -1

647 1812

Shim

DAS

6

9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK107

236

92073

38

M130388

198

92490

647.1814 Manufactured No

Each 28.0000 -1

647 1814

Gusset LH

DAS

6

9-89

MAY 15 2017

Location

Loc Qty

Loc Code

cck122A

28

92075

4

M130388

24

106843

647.1815 Manufactured No

Each 26.0000 -1

647 1815

Gusset RH

DAS

6

9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK110

2

92076

2

cck122A

24

M130388

24

106681

647.1818 Manufactured No

Each 25.0000 -1

647 1818

Nose Door Spacer

DAS

6

9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK110

25

92079

1

M130388

24

93302

Monday, May 15, 2017 10:39:09 AM

Shop Packet Print

Page 7

Picklist Print

Monday, May 15, 2017 10:39:09 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

647.1913 Manufactured No

Each 13.0000 -1

647 1913

Tee

MAY 15 2017

Location

Loc Qty

Loc Code

CCK093

13

DAS
6
9-89

114126

3

94139

92229

10

647.1914 Manufactured No

Each 1.0000 -1

647 1914

Bracket

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK110

1

109733

153314

1

~~190733~~

647.1915 Manufactured No

Each 22.0000 -1

647 1915

Support Angle

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK093

22

93416

114127

6

92230

4

M130388

12

647.2114 Manufactured No

Each 1.0000 -1

647 2114

Upper U Channel

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

cck001

1

7

147224

1

647.3201 Manufactured No

Each 0.0000 -1

647 3201

Grounding Cable Assembly

DAS
6
9-89

MAY 15 2017

123417

Picklist Print

Page 10

Monday, May 15, 2017 10:39:10 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

647.7821 Manufactured No

Each 7.0000 -1

647 7821

Eye Bolt Fitting LH

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK115

1

121378

1

CCK121

6

130388

6

647.7822 Manufactured No

Each 6.0000 -1

647 7822

Eye Bolt Fitting RH

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK115

6

M130388

6

647.7823 Manufactured No

Each 0.0000 -1

647 7823

Cross Bracket Aft

DAS
6
9-89

MAY 15 2017

647.7910 Manufactured No

Each 0.0000 -2

647 7910

Angle Bracket

DAS
6
9-89

MAY 15 2017

647.7911 Manufactured No

Each 5.0000 -1

647 7911

Bracket

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

CCK115

5

M130388

5

Monday, May 15, 2017 10:39:10 AM

Shop Packet Print

Page 10

Picklist Print

Page 11

Monday, May 15, 2017 10:39:10 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

647.7911 Manufactured No

Each 5.0000 -1

647 7911

Bracket

DAS 6 MAY 15 2017 9-89

Location

Loc Qty

Loc Code

CCK115

5

M130388

5

93383

647.7912 Manufactured No

Each 17.0000 -4

647 7912

Clip

DAS 6 MAY 15 2017 9-89

Location

Loc Qty

Loc Code

CCK115

17

157794

17

93312

647.7913 Manufactured No

Each 0.0000 -2

647 7913

Doubler

DAS 6 MAY 15 2017 9-89

647.7914

Manufactured No

Each 0.0000 -1

647 7914

Bracket

DAS 6 MAY 15 2017 9-89

647.7915

Manufactured No

Each 9.0000 -1

647 7915

Bracket

DAS 6 MAY 15 2017 9-89

Location

Loc Qty

Loc Code

cck116

9

M130388

9

93301

647.7916 Manufactured No

Each 16.0000 -2

647 7916

Bracket

DAS 6 MAY 15 2017 9-89

Location

Loc Qty

Loc Code

cck116

16

M130388

16

93287

Monday, May 15, 2017 10:39:10 AM

Shop Packet Print

Page 11

Picklist Print

Monday, May 15, 2017 10:39:10 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

647.7917	Manufactured	No	Each	13.0000	-1				
647 7917						**			
Bracket									

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
cck116	13	
131356	13	

93254

-1

MAY 15 2017

DAS 6 9-89

647.7918	Manufactured	No	Each	11.0000	-1				
647 7918						**			
Bracket									

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
cck116	11	
119630	11	

93385

-1

MAY 15 2017

DAS 6 9-89

647.7919	Manufactured	No	Each	6.0000	-1				
647 7919						**			
Shim									

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
cck116	6	
157799	6	

93337

-20

MAY 15 2017

DAS 6 9-89

647.8510	Manufactured	No	Each	4.0000	-20				
647 8510						**			
Insert									

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
cck116	4	
158923	4	

130388

-4

MAY 15 2017

DAS 6 9-89

647.8511	Manufactured	No	Each	13.0000	-4				
647 8511						**			
Insert									

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
cck116	13	
158626	13	

153194

DAS 6 9-89

Picklist Print

Monday, May 15, 2017 10:39:10 AM

Page 13

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

647.8512 Manufactured No

Each 10.0000 -2

647 8512

Insert

MAY 15 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

cck116

10

159419

10

130388

93635A212 Purchased No

Each 14.0000 -4

93635A212

Bolt

MAY 15 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

ST588

14

m134700

14

4

AN3-11A Purchased No

Each 280.0000 -4

AN3-11A

Bolt

MAY 15 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

over003

100

m136192

100

ST349

180

153855

180

135764

AN316C4R Purchased No

Each 17.0000 -4

AN316C4R

Nut, Jam

MAY 15 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

ST331

17

153850

17

135840

Picklist Print

Page 14

Monday, May 15, 2017 10:39:10 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

AN3-4A Purchased No

Each 418.0000 -2

AN3-4A******

Bolt

Location	Loc Qty	Loc Code
over003	379	
m137478	379	
ST350	39	
m136579	39	

DAS
6
9-89
MAY 15 2017

13504

AN44-12A Purchased No

Each 3.0000 -2

AN44-12A******

Eyebolt

Location	Loc Qty	Loc Code
ST339	3	
m137280	3	

DAS
6
9-89
MAY 15 2017

124131

AN4C7A Purchased No

Each 103.0000 -4

AN4C7A******

BOLT

Location	Loc Qty	Loc Code
OVER002	75	
m137361	75	
ST345	28	
m136295	28	

DAS
6
9-89
MAY 15 2017

135470

AN4CH6A Purchased No

Each 31.0000 -1

AN4CH6A******

Bolt

Location	Loc Qty	Loc Code
ST345	31	
123525	11	
m126176	20	

DAS
6
9-89
MAY 15 2017

123525

Monday, May 15, 2017 10:39:10 AM

Shop Packet Print

Page 14

Picklist Print

Monday, May 15, 2017 10:39:10 AM

Page 15

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

AN665-34R Purchased No

Each 14.0000 -3

AN665-34R

Clevis

MAY 15 2017

DAS 6 9-89

Location

Loc Qty

Loc Code

ST330

14

m137361

14

Each

14.0000

3
-1

MAY 15 2017

DAS 6 9-89

AN665-34R Purchased No

AN665-34R

Clevis

Location

Loc Qty

Loc Code

ST330

14

m137361

14

Each

209.0000

1
-1

MAY 15 2017

DAS 6 9-89

CCR264SS-3-03 Purchased No

CCR264SS-3-03

Cherry Rivet

Location

Loc Qty

Loc Code

FP001

14

m137164

14

LG001

13

m134023

13

ST321

182

m137164

182

135137

Picklist Print

Page 16

Monday, May 15, 2017 10:39:10 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

CCR264SS-3-03

Purchased

No

Each

209.0000

-23

CCR264SS-3-03******

Cherry Rivet

MAY 15 2017

DAS
6
9-89LocationLoc QtyLoc Code

FP001

14

m137164

14

LG001

13

m134023

13

ST321

182

m137164

182

124023

CCR274SS-3-03

Purchased

No

Each

65.0000

-4

CCR274SS-3-03******

Rivet

MAY 15 2017

DAS
6
9-89LocationLoc QtyLoc Code

ST321

65

123785

65

CR3212-5-06

Purchased

No

Each

98.0000

-2

CR3212-5-06******

Rivet

MAY 15 2017

DAS
6
9-89LocationLoc QtyLoc Code

ST320

98

123785

98

CR3213-4-05

Purchased

No

Each

0.0000

-8

CR3213-4-05******

RIVET

MAY 15 2017

DAS
6
9-89

Monday, May 15, 2017 10:39:10 AM

Shop Packet Print

Page 16

Picklist Print

Monday, May 15, 2017 10:39:10 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

CR3213-4-2 Purchased No

Each 174.0000 -4

CR3213-4-2

Cherry Rivet

MAY 15 2017

DAC
6
9-89

Location

Loc Qty

Loc Code

CCK003

100

m137412

100

134 058

ST320

74

m136986

74

CR3213-4-3 Purchased No

Each 320.0000 -24

CR3213-4-3

Rivet, Cherry

MAY 15 2017

DAC
6
9-89

Location

Loc Qty

Loc Code

CCK003

228

m136851

228

135 135

GA

92

m136042

92

CR3213-4-4 Purchased No

Each 361.0000 -16

CR3213-4-4

Rivet, Cherry

MAY 15 2017

DAC
6
9-89

Location

Loc Qty

Loc Code

CCK003

200

m137391

200

135 536

ST319

161

m136301

161

Picklist Print

Page 18

Monday, May 15, 2017 10:39:10 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

CR3213-4-6 Purchased No

Each 208.0000 -17

CR3213-4-6

DAS
6
9-89

Rivet

MAY 15 2017

Location Loc Qty Loc Code

CCK003 100

M136199 100

ST319 108

M131800 8

M135978 100

17

CR3213-5-3 Purchased No

Each 216.0000 -16

CR3213-5-3

DAS
6
9-89

Cherry Rivet

MAY 15 2017

Location Loc Qty Loc Code

CCK003 100

m137391 100

ST319 116

m136851 16

m137320 100

135408

CR3213-5-4 Purchased No

Each 105.0000 -12

CR3213-5-4

DAS
6
9-89

Cherry Rivet

MAY 15 2017

Location Loc Qty Loc Code

ST319 93

123785 1

m128199 92

WA003 12

117543 12

123785

Picklist Print

Monday, May 15, 2017 10:39:11 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

CR3522-4-3	Purchased	No	Each	2.0000	-8	**	DAS 6 9-89	
CR3522-4-3								
Rivet								
		<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>		
		ST318		2				
		124876		2				
CR3522-5-3	Purchased	No	Each	60.0000	-8	**	DAS 6 9-89	MAY 15 2017
CR3522-5-3								
Rivet								
		<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>		
		ST317		60				
		m136199		60				
CR3523-4-3	Purchased	No	Each	38.0000	-4	**	DAS 6 9-89	MAY 15 2017
CR3523-4-3								
Rivet								
		<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>		
		ST317		38				
		m129764		38				
CR3523-4-4	Purchased	No	Each	65.0000	-22	**	DAS 6 9-89	MAY 15 2017
CR3523-4-4								
Rivet								
		<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>		
		ST317		65				
		m127255		65				
CR3523-4-4	Purchased	No	Each	65.0000	-2	**	DAS 6 9-89	MAY 15 2017
CR3523-4-4								
Rivet								
		<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>		
		ST317		65				
		m127255		65				

Picklist Print

Page 20

Monday, May 15, 2017 10:39:11 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

CR3523-5-3
Purchased No
CR3523-5-3
Rivet

Location	Loc Qty	Loc Code
ST317	36	
m134962	36	

**

DAS
6
9-89
MAY 15 2017

LN9025-0820K
Purchased No
I N9025-0820K
Lock Tab Washer

Location	Loc Qty	Loc Code
ST564	34	
M136620	34	

**

DAS
6
9-89
MAY 15 2017

LN9037-08018
Purchased No
I N9037-08018
Screw

Location	Loc Qty	Loc Code
ST564	22	
m137315	22	

**

DAS
6
9-89
MAY 15 2017

LN9037-08018
Purchased No
I N9037-08018
Screw

Location	Loc Qty	Loc Code
ST564	22	
m137315	22	

**

DAS
6
9-89
MAY 15 2017

Picklist Print

Page 21

Monday, May 15, 2017 10:39:11 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS21042L08

Purchased

No

Each

968.0000

-5

MS21042I 08

Nut

DAS
9-88 MAY 15 2017

Location

Loc Qty

Loc Code

GA

108

m135274

6

m135978

102

ST303

860

m137391

560

m137464

300

135766

MS21042L08

Purchased

No

Each

968.0000

-5

MS21042I 08

Nut

DAS
9-88 MAY 15 2017

Location

Loc Qty

Loc Code

GA

108

m135274

6

m135978

102

ST303

860

m137391

560

m137464

300

135766

MS21042L3

Purchased

No

Each

1,203.000

-24

MS21042I 3

Nut

Location

Loc Qty

Loc Code

FP001

91

m135945

91

GA

464

m134360

102

M136665

362

ST303

648

m137321

648

135767

Monday, May 15, 2017 10:39:11 AM

Shop Packet Print

Page 21

Picklist Print

Page 22

Monday, May 15, 2017 10:39:11 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS21042L3 Purchased No

Each 1,203.000 -11

MS21042L3

DAS
6
9-89

Nut

Location Loc Qty Loc Code

FP001 91

m135945 91

GA 464

m134360 102

M136665 362

ST303 648

m137321 648

135350

MS21042L4 Purchased No

Each 2,792.000 -4

MS21042L4

DAS
6
9-89

Nut

Location Loc Qty Loc Code

FP001 10

m133363 10

GA 148

m135058 148

OVER007 1400

m137371 1000

m137402 400

ST303 1234

m137321 1234

135774

MAY 15 2017

Monday, May 15, 2017 10:39:11 AM

Shop Packet Print

Page 22

Picklist Print

Page 23

Monday, May 15, 2017 10:39:11 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS21042L5 Purchased No

Each 191.0000 -4

MS21042L5

MAY 15 2017

DAS
6
9-89

Nut

Location	Loc Qty	Loc Code
GA	16	
m127813	16	
ST303	175	
m137075	25	
m137361	150	

135297

MS21047-3 Purchased No

Each 235.0000 -6

MS21047-3

MAY 15 2017

DAS
6
9-89

Nut Plate

Location	Loc Qty	Loc Code
ST301	235	
m137075	85	
m137459	150	

135774
135774

MS21047-3 Purchased No

Each 235.0000 -6

MS21047-3

MAY 15 2017

DAS
6
9-89

Nut Plate

Location	Loc Qty	Loc Code
ST301	235	
m137075	85	
m137459	150	

135603

MS21266-2N Purchased No

Each 36.0000 -1

MS21266-2N

MAY 15 2017

DAS
6
9-89

Grommet

Location	Loc Qty	Loc Code
ST294	36	
123900	36	

130388

Monday, May 15, 2017 10:39:11 AM

Shop Packet Print

Page 23

Picklist Print

Monday, May 15, 2017 10:39:11 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS24694-S54

Purchased

No

Each

74.0000

-5

MS24694-S54

SCREW

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

ST284

74

153846

74

5

MS27039-08-07

Purchased

No

Each

91.0000

-1

MS27039-08-07

SCREW

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

ST278

91

m132035

91

1

MS27039-08-13

Purchased

No

Each

306.0000

-4

MS27039-08-13

Screw

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

ST278

306

153849

306

124326

MS27039-08-19

Purchased

No

Each

448.0000

-5

MS27039-08-19

Screw

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

GA

30

m135948

26

m137178

4

over006

200

m137464

200

ST277

218

m137320

18

m137361

200

135865

Picklist Print

Monday, May 15, 2017 10:39:11 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS27039-1-07

Purchased

No

Each

62.0000

-3

DAS
6
9-89

MAY 15 2017

MS27039-1-07

Screw

**

Location

Loc Qty

Loc Code

GA

48

m137320

48

ST281

14

m135948

14

MS27039-1-09

Purchased

No

Each

67.0000

-12

DAS
6
9-89

MAY 15 2017

MS27039-1-09

Screw

**

Location

Loc Qty

Loc Code

FP001

17

18057

17

GA

50

124859

50

MS27039-1-10

Purchased

No

Each

281.0000

-6

DAS
6
9-89

MAY 15 2017

MS27039-1-10

SCREW

**

Location

Loc Qty

Loc Code

GA

15

m129541

15

ST280

266

m137164

266

MS27039-1-12

Purchased

No

Each

78.0000

-2

DAS
6
9-89

MAY 15 2017

MS27039-1-12

Screw

**

Location

Loc Qty

Loc Code

ST280

78

m136537

28

m137320

50

Picklist Print

Monday, May 15, 2017 10:39:11 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS27039-1-14

Purchased

No

Each

628.0000

-4

MS27039-1-14

Screw

MAY 15 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

GA

90

120449

90

over006

300

124326

300

ST280

238

124326

238

Each

129.0000

-1

MS27039-1-15

Purchased

No

MS27039-1-15

Screw

MAY 15 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

GA

65

m127916

1

m136554

64

ST280

64

m136406

64

Each

149.0000

-4

MS27039-1-16

Purchased

No

MS27039-1-16

Screw

MAY 15 2017

68-6
9
DAS

Location

Loc Qty

Loc Code

over006

50

m137061

50

ST280

99

m137320

99

Picklist Print

Monday, May 15, 2017 10:39:11 AM

Page 27

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS27039-1-17

Purchased

No

Each

148.0000

-2

MS27039-1-17

Screw (601.1954)

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

ST280

148

m127831

148

Each

1,620.000

-2

MS27039-1-18

Purchased

No

MS27039-1-18

Screw

120142

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

GA

239

123522

39

124326

200

over006

1200

124326

1200

ST280

181

124326

181

NAS1149C0432R

Purchased

No

Each

1,774.000

-12

NAS1149C0432R

WASHER

MAY 15 2017

Location

Loc Qty

Loc Code

GA

357

m134676

357

ST260a

1000

m137459

1000

ST266

417

m136986

417

135929

DAS
6
9-89

Picklist Print

Monday, May 15, 2017 10:39:11 AM

Page 28

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

NAS1149F0332P

Purchased

No

Each

2,677.000

-89

NAS1149F0332P

Washer

Location

Loc Qty

Loc Code

GA

275

m133709

275

ST260a

1800

m137412

1800

ST262

602

m137075

602

NAS1149F0532P

Purchased

No

Each

1,597.000

-4

NAS1149F0532P

Washer

Location

Loc Qty

Loc Code

ST260a

600

m133725

600

ST262

997

18057

997

NAS1149FN832P

Purchased

No

Each

2,058.000

-25

NAS1149FN832P

Washer

Location

Loc Qty

Loc Code

GA

358

M135058

208

M136182

40

M136866

110

ST263

1700

M137412

1700

DAS 6-89 MAY 19 2017

135544

DAS 6-89 MAY 15 2017

4

DAS 6-89 MAY 15 2017

135605

Monday, May 15, 2017 10:39:12 AM

Shop Packet Print

Page 28

Picklist Print

Monday, May 15, 2017 10:39:12 AM

Work Order ID: 161368

161368

Parent Item: 647.7304

647 7304

Parent Item Name: EC135 T2/P2 Cable Cutters System

Start Date: 5/15/2017

Required Date: 5/15/2017

Start Qty: 1.00

Required Qty: 1.00

NAS6603-12

Purchased

No

Each

111.0000

-4

NAS6603-12

Bolt

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

st552

111

123900

76

m136301

35

4

NAS6603-16

Purchased

No

Each

56.0000

-4

NAS6603-16

Bolt

DAS
6
9-89

MAY 15 2017

Location

Loc Qty

Loc Code

st552

56

153860

6

m133523

50

126/99

161368

Done

Reason	Parent Item ID	Lot Qty	Lot Nbr	Lot Trans Date	Trans Type
153279	600.0990	-1	M135213	11/16/2016 15:29	Issue
153279	600.0991	-1	m135213	11/16/2016 15:29	Issue
153279	600.1012	-1	m135600	11/16/2016 15:29	Issue
153279	601.2045	-1	m135628	11/16/2016 15:29	Issue
153279	601.2375	-3	91708	11/16/2016 15:29	Issue
153279	601.2999	-3	91707	11/16/2016 15:29	Issue
153279	601.3004	-2	M130388	11/16/2016 15:29	Issue
153279	601.3005	-2	151173	11/16/2016 15:29	Issue
153279	601.3006	-2	M130388	11/16/2016 15:29	Issue
153279	601.3011	-1.4	M130388	11/16/2016 15:29	Issue
153279	601.3902	-1	147212	11/16/2016 15:29	Issue
153279	601.3902	-1	153184	11/23/2016 14:51	Issue
153279	647.0112	-4	151352	11/16/2016 15:29	Issue
153279	647.1601	-1	148295	11/16/2016 15:29	Issue
153279	647.1602	-1	92479	11/16/2016 15:29	Issue
153279	647.1610	-1	125082	11/16/2016 15:29	Issue
153279	647.1702	-1	154422	2/8/2017 15:20	Issue
153279	647.1702	-2	153324	1/20/2017 11:24	Issue
153279	647.1702	-2	153187	12/6/2016 9:02	Issue
153279	647.1810	-1	92070	11/16/2016 15:29	Issue
153279	647.1811	-1	93341	11/16/2016 15:29	Issue
153279	647.1811	-1	92072	11/16/2016 15:29	Issue
153279	647.1812	-1	92490	11/16/2016 15:29	Issue
153279	647.1812	-2	92073	11/16/2016 15:29	Issue
153279	647.1812	-10	93192	11/16/2016 15:29	Issue
153279	647.1814	-1	106843	11/16/2016 15:29	Issue
153279	647.1815	-1	106681	11/16/2016 15:29	Issue
153279	647.1818	-1	93302	11/16/2016 15:29	Issue
153279	647.1913	-1	94139	11/16/2016 15:29	Issue
153279	647.1914	-1	109733	11/16/2016 15:29	Issue
153279	647.1915	-1	93416	11/16/2016 15:29	Issue
153279	647.2114	-1	147224	11/16/2016 15:29	Issue
153279	647.3201	-1	123417	11/16/2016 15:29	Issue
153279	647.7501	-1	153327	1/13/2017 11:06	Issue
153279	647.7701	-2	153191	1/16/2017 8:53	Issue
153279	647.7701	-2	147523	12/14/2016 14:48	Issue
153279	647.7702	-2	147297	1/16/2017 8:34	Issue
153279	647.7702	-2	146723	11/16/2016 15:29	Issue
153279	647.7819	-1	130656	11/16/2016 15:29	Issue
153279	647.7821	-1	M130388	11/16/2016 15:29	Issue
153279	647.7822	-1	123827	11/16/2016 15:29	Issue
153279	647.7823	-1	146665	11/16/2016 15:29	Issue
153279	647.7910	-2	93329	11/16/2016 15:29	Issue
153279	647.7911	-1	93383	11/16/2016 15:29	Issue
153279	647.7911	-1	M130388	11/16/2016 15:29	Issue
153279	647.7912	-4	93312	11/16/2016 15:29	Issue

153279	647.7913	-2	93270	11/16/2016 15:29	Issue
153279	647.7914	-1	93215	11/16/2016 15:29	Issue
153279	647.7915	-1	93301	11/16/2016 15:29	Issue
153279	647.7916	-2	93287	11/16/2016 15:29	Issue
153279	647.7917	-1	93254	11/16/2016 15:29	Issue
153279	647.7918	-1	93385	11/16/2016 15:29	Issue
153279	647.7919	-1	93337	11/16/2016 15:29	Issue
153279	647.8510	-20	M130388	11/16/2016 15:29	Issue
153279	647.8511	-4	153194	12/13/2016 13:11	Issue
153279	647.8512	-2	M130388	11/16/2016 15:29	Issue
153279	93635A212	-4	m134700	11/16/2016 15:29	Issue
153279	AN3-11A	-4	m135767	11/16/2016 15:29	Issue
153279	AN316C4R	-4	m135840	11/16/2016 15:29	Issue
153279	AN3-4A	-2	m135704	11/16/2016 15:29	Issue
153279	AN44-12A	-2	124131	11/16/2016 15:29	Issue
153279	AN4C7A	-4	m135470	11/16/2016 15:29	Issue
153279	AN4CH6A	-1	123525	11/16/2016 15:29	Issue
153279	AN665-34R	-3	M135603	11/16/2016 15:29	Issue
153279	AN665-34R	-1	M135948	11/16/2016 15:29	Issue
153279	CCR264SS-3-03	-23	m134023	11/17/2016 7:31	Issue
153279	CCR264SS-3-03	-1	m135127	11/17/2016 7:31	Issue
153279	CCR274SS-3-03	-4	123785	11/17/2016 7:31	Issue
153279	CR3212-5-06	-2	120933	11/17/2016 7:31	Issue
153279	CR3213-4-05	-8	m135407	11/17/2016 7:31	Issue
153279	CR3213-4-2	-4	m134058	11/17/2016 7:31	Issue
153279	CR3213-4-3	-24	m135135	11/17/2016 7:31	Issue
153279	CR3213-4-4	-16	M135536	11/17/2016 7:31	Issue
153279	CR3213-4-6	-17	M131800	11/17/2016 7:31	Issue
153279	CR3213-5-3	-16	m135408	11/17/2016 7:31	Issue
153279	CR3213-5-4	-12	123785	11/17/2016 7:31	Issue
153279	CR3522-4-3	-8	124876	11/17/2016 7:31	Issue
153279	CR3522-5-3	-8	m136199	11/22/2016 15:23	Issue
153279	CR3523-4-3	-4	m129764	11/17/2016 7:31	Issue
153279	CR3523-4-4	-2	m130388	11/17/2016 7:31	Issue
153279	CR3523-4-4	-22	124259	11/17/2016 7:31	Issue
153279	CR3523-5-3	-8	m134962	11/17/2016 7:31	Issue
153279	LN9025-0820K	-8	m136136	11/17/2016 7:31	Issue
153279	LN9037-08018	-4	m136172	11/22/2016 11:14	Issue
153279	LN9037-08018	-4	m136136	11/17/2016 7:31	Issue
153279	MS21042L08	-5	m135766	11/17/2016 7:31	Issue
153279	MS21042L08	-5	m135766	11/17/2016 7:31	Issue
153279	MS21042L3	-24	m135767	11/17/2016 7:31	Issue
153279	MS21042L3	-11	m135530	11/17/2016 7:31	Issue
153279	MS21042L4	-4	m135774	11/17/2016 7:31	Issue
153279	MS21042L5	-4	m135297	11/17/2016 7:31	Issue
153279	MS21047-3	-6	m135603	11/17/2016 7:31	Issue
153279	MS21047-3	-6	m135774	11/17/2016 7:31	Issue

153279	MS21266-2N	-1	M130388	11/17/2016 7:31	Issue
153279	MS24694-S54	-5	m135672	11/17/2016 7:31	Issue
153279	MS27039-08-07	-1	m132035	11/17/2016 7:31	Issue
153279	MS27039-08-13	-4	124326	11/17/2016 7:31	Issue
153279	MS27039-08-19	-5	m135865	11/17/2016 7:31	Issue
153279	MS27039-1-07	-3	m135948	11/17/2016 7:31	Issue
153279	MS27039-1-09	-12	m125646	11/17/2016 7:31	Issue
153279	MS27039-1-10	-6	m135603	11/17/2016 7:31	Issue
153279	MS27039-1-12	-2	m135566	11/17/2016 7:31	Issue
153279	MS27039-1-14	-4	124326	11/17/2016 7:31	Issue
153279	MS27039-1-15	-1	m134852	11/17/2016 7:31	Issue
153279	MS27039-1-16	-4	m135566	11/17/2016 7:31	Issue
153279	MS27039-1-17	-2	120142	11/17/2016 7:31	Issue
153279	MS27039-1-18	-2	124326	11/17/2016 7:31	Issue
153279	NAS1149C0432R	-12	m135979	11/17/2016 7:31	Issue
153279	NAS1149F0332P	-89	m135544	11/17/2016 7:31	Issue
153279	NAS1149F0532P	-4	18057	11/17/2016 7:31	Issue
153279	NAS1149FN832P	-25	M135603	11/17/2016 7:31	Issue
153279	NAS6603-12	-4	123900	11/17/2016 7:31	Issue
153279	NAS6603-16	-4	m128199	11/17/2016 7:31	Issue

Reason	Parent Item ID	Lot Qty	Lot Nbr	Lot Trans Date	Trans Type
159888	647.7304	-1	153279	4/19/2017 13:05	Rework
159888	647.7501	-1	159418	5/10/2017 9:48	Issue
159888	AN665-34R	-4	m137361	5/4/2017 9:54	Issue